

Youth Shelter

AS Matthews

To remove back portion of cedar shingles,
then damaged sterling board and oak wall
plate plus rafter and replace with like for like
materials. Efforts would be made to clean
smoke damaged under side of board as
instructed but from past experience this does
not remove all of blackened damage.

#####